



**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

September 29, 1982  
RBG-13,441  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1  
Locket No. 50-458  
Final Report/DR-58



On June 3, 1982, Gulf States Utilities Company (GSU) notified the Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning indications found on shop radiographs of containment penetration bellows (DR-58).

GSU has completed its investigation and determined that no reportable deficiency exists. A review of field radiographs performed subsequent to the shop radiographs in question revealed that no indications remained. This concludes GSU's response on this subject.

Sincerely,

*for* J. E. Booker  
Manager-Engineering & Licensing  
River Bend Nuclear Group

JEB/LAE/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

R. L. Brown (RRI)

IE 27

8210050219 820929  
PDR ADOCK 05000458  
S PDR