



Duquesne Light

Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

October 22, 1990
ND3MNC:3052

Beaver Valley Power Station, Unit No. 2
Docket No. 50-412, License No. NPF-73
Revised Special Report

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Unit #2 Technical Specification 3/4.4.5, "Steam Generators," Surveillance Requirement 4.4.5.5.a, the following revised Special Report is submitted. This revised report documents the correction of an error, listing the steam generators which received a leak limiting plug, during the Second Refueling Outage.

On September 30, 1990, the inservice inspection of twenty percent of the tubes in steam generators 2RCS-SG21B (S/G B) and 2RCS-SG21C (S/G C) was completed.

The inspection results identified no indications of tube wall degradation of forty (40) percent or greater. Two (2) tubes were plugged (leak limiting plugs in the cold leg) as a result of an analysis conducted to determine which tubes could be susceptible to vibration induced fatigue. The tubes were located in Row 9, Column 84 in each steam generator (S/G A and C).

9010310098 901022
PDR ADOCK 05000412
S PDC

IE22
'10


October 22, 1990

ND3MNO:3052

Page 2

Additionally, plug retainers were installed in nine Westinghouse ribbed plugs on the outlet side (plug retainers had been installed on the inlet plugs during the first refueling). Three inlet side Babcock & Wilcox rolled plugs were replaced with plugs of Inconel 690.

Very truly yours.



T. P. Noonan
General Manager
Nuclear Operations

JGT/sl

Attachment

October 22, 1990

ND3MNO:3052

Page 3

cc: Mr. T. T. Martin, Regional Administrator
United States Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 19406

C. A. Roteck, Ohio Edison
76 S. Main Street
Akron, OH 44308

Mr. A. DeAgazio, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, DC 20555

J. Beall, Nuclear Regulatory Commission
BVPS Senior Resident Inspector

Larry Beck
Cleveland Electric
6200 Oak Tree Blvd.
Independence, Ohio 44101

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle
Factory Mutual Engineering
680 Anderson Drive #BLD10
Pittsburgh, PA 15220-2773

Mr. J. N. Steinmetz, Operating Plant Projects Manager
Mid Atlantic Area
Westinghouse Electric Corporation
Energy Systems Service Division
Box 355
Pittsburgh, PA 15230

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. Richard Janati
Department of Environmental Resources
P. O. Box 2063
16th Floor, Fulton Building
Harrisburg, PA 17120

Director, Safety Evaluation & Control
Virginia Electric & Power Co.
P. O. Box 26666
One James River Plaza
Richmond, VA 23261

October 22, 1990

ND3MNO:3052

Page 4

cc: W. Hartley
Management Analysis Company
112671 High Bluff Drive
San Diego, CA 92130-2025

J. M. Riddle
NUS Operating Service Corporation
Park West II
Cliff Mine Road
Pittsburgh, PA 15275