



September 24, 1982

Log No. K82-1394
File: RR 2 (NP-33-82-46)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler,
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-042
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: August 27, 1982

Enclosed are three copies of Licensee Event Report 82-042 with supplemental information sheets which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray /smq

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

8210050355 820924
PDR ADOCK 05000346
S PDR

SEP 29 1982

IE22