

APR 07 1994

DCS

Docket Nos. 50-245
50-336
50-423

Mr. John F. Opeka
Executive Vice President - Nuclear
Northeast Nuclear Energy Company
P. O. Box 270
Hartford, Connecticut 06141-0270

Dear Mr. Opeka:

Subject: NRC Combined Inspection Nos. 50-245/94-16; 50-336/94-15; 50-423/94-14

An announced radiological controls, solid radioactive waste management, and radioactive materials transportation program inspection was conducted during the period March 22-25, 1994, by Messrs. R. L. Nimitz and L. Eckert at the Millstone Nuclear Power Station Units 1, 2, and 3. The findings of the inspection were discussed with Messrs. R. Factora and F. Dacimo and others at the conclusion of the inspection on March 25, 1994.

Areas reviewed during the inspection are important to health and safety and are discussed in the enclosed inspection report. The areas reviewed included previous findings; changes; audits and appraisals; organization and staffing; training and qualification; external and internal exposure controls; radioactive material and contamination controls; radioactive waste handling, storage processing and shipping; and station conditions. Also reviewed were routine radiological controls activities at Units 1, 2, and 3.

The inspection identified that generally very good radioactive waste handling, storage, processing, and transportation programs were implemented at the Millstone Station. The programs were generally well managed with a good level of technical expertise available to support these programs. Radiological controls for on-going activities at Unit 1, 2 and 3 were generally effective. Three violations of your radiation protection procedures, identified by your staff, were reviewed. Consistent with the criteria specified in 10 CFR 2, Appendix B, these violations are not cited. One unresolved item, associated with contamination of a sump in Unit 3, is discussed in this report. We will review this matter during a subsequent inspection.

150019

OFFICIAL RECORD COPY

IE 06

9404180022 940407
PDR ADOCK 05000245
Q PDR

No response to this letter is required. Your cooperation with us is appreciated.

Sincerely,

Original Signed By:
James H. Joyner

James H. Joyner, Chief
Facilities Radiological Safety
and Safeguards Branch
Division of Radiation Safety
and Safeguards

Enclosure: NRC Combined Inspection Report Nos. 50-245/94-16;
50-336/94-15; 50-423/94-14

cc w/encl:

S. E. Scace, Vice President, Nuclear Operations Services
D. B. Miller, Senior Vice President, Millstone Station
H. F. Haynes, Nuclear Unit Director
G. H. Bouchard, Nuclear Unit Director
F. R. Dacimo, Nuclear Unit Director
R. M. Kacich, Director, Nuclear Planning, Licensing and Budgeting
J. Solymosy, Director Nuclear Quality and Assessment Services
Gerald Garfield, Esquire
Nicholas Reynolds, Esquire
K. Abraham, PAO (2)
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
State of Connecticut SLO Designee
NRC Resident Inspector

Northeast Nuclear Energy Company

3

bcc w/encl:

Region I Docket Room (with concurrences)

L. Doerflein, RI

bcc w/encl (VIA E-MAIL)

J. Stolz, NRR/PD I-4

V. McCree, OEDO

G. Vissing, PM, NRR

V. Rooney, PM, NRR

D. Jaffe, PM, NRR

J. Anderson, NRR

M. Shannon, NRR/ILPB

RI:DRSS


for Eckert



04/4/94

RI:DRSS

for Nimitz



04/4/94

RI:DRSS


for Bores



04/7/94

RI:DRSS

Joyner



04/7/94

OFFICIAL RECORD COPY

OFFICIAL RECORD COPY