



Florida Power

CORPORATION
Crystal River Unit 3
Docket No. 50-302

April 12, 1994
3F0494-06

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Reference: NRC to FPC letter Dated March 4, 1994
Inspection Report No. 50-302/94-01

Dear Sir:

Florida Power Corporation (FPC) provides the attached as our response to the exercise weakness identified in the referenced Inspection Report.

Sincerely,

P. M. Beard, Jr.
Senior Vice President
Nuclear Operations

PMB/RLM:ff

Attachment

xc: Regional Administrator, Region II
NRR Project Manager
Senior Resident Inspector

180042

TE01

FLORIDA POWER CORPORATION
NRC INSPECTION REPORT NO. 50-302/94-01
RESPONSE TO EXERCISE WEAKNESS

EXERCISE WEAKNESS 50-302/94-01-02

Onsite accountability of personnel within the protected area was not completed within approximately 30 minutes.

RESPONSE

The exercise weakness was primarily due to a misunderstanding by security personnel as to the requirements for determining accountability. Individuals were not only identified as being missing, but were then physically located as well before accountability was announced as complete. Contributing to the delay was unanticipated computer process printer time requirements. This equipment had not previously been utilized in this capacity.

A procedural change has been made to Emergency Plan Implementing Procedure EM-205, "Emergency Assembly, Evacuation, and Accountability of Personnel Within the Protected Area" that clarifies the definitions and requirements for onsite accountability. Additionally, a computer software change will be incorporated to reduce both printer operation time and hard copy review time. This software enhancement will be incorporated into the Security Computer by August 31, 1994.