

APPENDIX A
NOTICE OF VIOLATION

Consolidated Edison Company
Indian Point Unit 2

Docket No. 50-247
License No. DPR-26

As a result of the inspection conducted on August 1-31, 1982, and in accordance with NRC Enforcement Policy 47 FR 997(March 9, 1982), the following violation was identified:

10 CFR 50, Appendix B, Criterion V, states in part, "Activities affecting quality shall be prescribed by documented instructions, procedures...of a type appropriate to the circumstances..."

The licensee's Quality Assurance Program for Operating Nuclear Plants, CI-240-1, Section X, requires that the licensee's procedures reflect and incorporate technical specification engineering requirements and parameter limits applicable during the operation of the plant.

Technical Specifications, Section 1.7d, defines containment integrity as a condition which exists when all automatic containment isolation valves are either operable or in the closed position. Technical Specifications, Section 3.6.A does not provide for reopening failed automatic containment isolation valves.

Contrary to the above, Procedure A-26, Loss of Containment Integrity, Revision 0, permits periodic reopening of a failed automatic containment isolation valve during plant operations.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Consolidated Edison Company of New York, Inc., is hereby required to submit to this office within thirty days of the date of the Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending your response time.