NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

	CONTROL BL CK:
0 1	M IP A L 1 2 00 -0 0 00 - 0 0 3 41 1 1 1 1 6 57 CAT 58
CON'T	REPORT
0 2	During NRC Inspection 82-15, it was determined that four fire doors manufac-
0 3	tured by Protective Materials Company, Inc. do not have documentation to
0 4	confirm they have been tested and approved by a nationally recognized labo-
0 5	atory. Accordingly, fire doors 44, 52, 106 and 108 have been declared
0 6	[inoperable and hourly inspections established in accordance with TS 3.22.5.1]
0 7	Condition reportable per TS 6.9.2.b(2).
0 8 7 8	9
0 9	CODE CODE SUBCODE SUBC
	DER RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 2 6 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRO4 PRIME COMP. TAKEN ACTION ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER LX 18 X 19 X 20 Z 20 Z 21 O O O O N 23 X 25 X 9 9 9 9 2 (26) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	Event occurred because Protective Materials failed to obtain proper certifi-
111	cation after modifying the doors. Original door design had been certified,
1 2	but subsequent changes were not adequately tested. Proper certification
1 3	will be obtained or the doors will be replaced with certified doors.
7 8	9 80
1 5	STATUS POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 G 28 0 0 0 29 NA DISCOVERY DESCRIPTION 32 9 10 12 13 NA 45 46 NRC Inspection
	CTIVITY CONTENT ELEASE OF RELEASE AMOUNT OF ACTIVITY (35) NA N
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA PERSONNEL INJURIES NA 80
1 8	NUMBER DESCRIPTION (4) NA
	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA NA
20,	PUBLICITY ISSUED DESCRIPTION 45 NA NA SE ONLY NA 68 69 80