

SEP 30 1982

Docket Nos. 30-00349  
30-02468

License Nos. 29-03198-02  
29-03198-03

Alfred J. Swyer, M.D., P.A.  
Diagnostic Imaging  
307 60th Street  
West New York, New Jersey 07093

Dear Dr. Swyer:

Subject: Combined Inspection Nos. 30-00349/82-01 and 30-02468/82-01

This refers to your letter dated September 13, 1982, in response to our letter dated July 23, 1982.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

From a September 3, 1982, telephone conversation between yourself and Dr. Laurence F. Friedman of this office, we understand that you will, in conjunction with your consultant physicist, perform monthly audits of your licensed program to assure that violations of NRC requirements do not occur. We will review this matter during the next inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:  
John D. Kinneman

*for*

Thomas T. Martin, Director  
Division of Engineering and  
Technical Programs

Enclosure: Reg. Guide 8.23, Safety Surveys at Medical Institutions

cc w/encl:  
Public Document Room (PDR)  
Nuclear Safety Information Center (NSIC)  
State of New Jersey

bcc w/encl:  
Region I Docket Room (with concurrences)  
~~Chief, Operational Support Section (w/o encl)~~

RI:DETP  
Stearns/dmg 9/24/82  
RI:DETP  
Kinneman 9/27/82

OFFICIAL RECORD COPY

8210060337 820930  
NMS LIC30  
29-03198-02 PDR

1E:07