

NJK-82-428

September 27, 1982

J. Keppler, Regional Director Office of Inspection and Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Reference: Quad-Cities Nuclear Power Station

Docket Number 50-254, DPR-29, Unit One

Appendix A. Section 4.7.A.2.i

Enclosed please find Reportable Occurrence Report Number RO 82-26/03L-0 for Quad-Cities Nuclear Power Station. This report addresses the first failure of the Unit One EOC 6 Refueling Outage Local Leak Rate Testing Program. All additional failures will be reported in a final supplemental report following all determinations of failure modes and corrective actions, as discussed with NRC site representative and the NRC Region III office.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.2.b; operation in a degraded mode as permitted by a limiting condition of operation.

Very truly yours,

COMMONWEALTH EDISON COMPANY QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis

Station Superintendent

NJK: HGL/bb

Enclosures

cc T. J. Rausch N. Chrissclimos INPO Records Center

OCT 1 1982