



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

APR 13 1994

Docket: 030-32323  
License: IDA-04-16

University of Idaho  
ATTN: G. Wallace, Financial Vice President  
Moscow, Idaho 83843

SUBJECT: NRC INSPECTION REPORT 030-32323/94-01

This refers to the routine, unannounced inspection conducted by Mr. Robert A. Brown of this office on March 15 and 17, 1994. The inspection included a review of activities authorized by Byproduct Materials License IDA-04-16. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector reviewed with your Radiation Safety Officer (RSO) the status of your license renewal package. The RSO stated that this package is near completion and will be submitted to the NRC in the near future. Also reviewed were the authority and functions of the Radiation Safety Committee (RSC). It appears that the RSC has sufficient and appropriate authority to oversee the radiation safety program. A review of minutes of RSC meetings indicate they take a very active role in reviewing and approving requests from the research staff to use radioisotopes.

Also reviewed were the actions you had taken with respect to the violations observed during our previous inspection conducted on June 25, 1991. The inspection verified that the corrective actions for these violations had been implemented as stated in your reply dated August 21, 1991, and that these actions were effective.


In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

9404200195 940413  
PDR ADOCK 03032323  
C PDR

IE07  
1/0

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

A handwritten signature in cursive script that reads "Charles L. Cain".

Charles L. Cain, Chief  
Nuclear Materials Inspection Branch

cc:  
Idaho Radiation Control Program Director

bcc:  
DMB - Original (IE-07)  
LJCallan  
SJCcollins  
RAScarano, DRSS/RIV  
MMessier, OC/LFDCB (4503)  
\*WLFisher  
\*CLCain  
\*RABrown  
\*NMIB  
\*MIS System  
\*RIV Files (2)  
  
\*W/IFS Form

RIV:NMIB	C:NMIB <i>WRC</i>			
RABrown <i>RAB</i>	CLCain			
04/12/94	04/12/94			

bcc:  
DMB - Original (IE-07)  
LJCallan  
SJCcollins  
RAScarano, DRSS/RIV  
MMessier, OC/LFDCB (4503)  
\*WLFisher  
\*CLCain  
\*RABrown  
\*NMIB  
\*MIS System  
\*RIV Files (2)  
  
\*W/IFS Form

RIV:NMIB	C:NMIB <i>rc</i>			
RABrown <i>RAB</i>	CLCain			
04/12/94	04/12/94			