NRC Form 591			U.E. MUCHEAR RECIT ATORY COMMISSION
(12-81)- 10 CFR 2.201	SAFETY IN	SPECTION	DOD DO B
Missovei Precisión (905 E. 340 ST. JOPAIN MO. 64801		2. REGIONAL OFFICE U.S. NUCLEAR REGION III 799 ROOSEVEL GLEN ELLYN,	REGULATORY COMMISSION
3. DOCKET NUMBER(S) 030 - 08655	4. LICENSE NUMBER(S)	-0/	November 13, 1990
those actions at this time. 3. During this inspection certain of your activity THIS IS A NOTICE OF VIOLATION which	ons and the conditions of you inel, and observations by the i itions were observed. ve taken to correct the violatio ties, as checked below, were in h is required to be posted in a	r license. The inspection nspector. The findings i ons identified during the n violation of NRC requirecordance with 10 CFR	n consisted of selective examinations of procedures as a result of this inspection are as follows: last inspection. We have no further questions on irements.
		License Condition Nur	of sealed sources were not performed at the proper andition ^{so} umber were not performed at the proper were not performed at the proper-
F. Reports or notifications of with 10 CFR		License Condition Nun	
Br. FAILURE TO RE NAC WASHINGTON		TERMINAT	SUXE DATA TO U.S.
□ĸ24+15152+0	901113 1 PDC		
I hereby state that within 30 days the actions description is statement of corrective actions is made in according the NRC.			Multiple submitted unless required by