



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

111 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

APR 18 1994

Docket: 030-28835
License: 35-23193-01

Edwards Pipeline Testing, Inc.
ATTN: Don Earl Edwards, President
P.O. Box 470978
Tulsa, Oklahoma 74147-0978

SUBJECT: NRC INSPECTION REPORT 030-28835/94-01

This refers to the routine, unannounced inspection conducted by Mr. Robert A. Brown of this office on March 31, 1994. The inspection included a review of activities authorized by Byproduct Materials License 35-23193-01. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector reviewed the management of your internal audit program and noted that these audits are conducted by field supervisors at temporary jobsites throughout the country. The results of these audits appeared thorough and timely. Also noted by the inspector was the increased staff devoted to radiation safety tasks. You currently have one to one and a half full-time employees involved in the operation of the radiation safety program. In reviewing records the inspector observed that your computer based system has provided you with an efficient and comprehensive records management system. The level of management attention devoted to the radiation safety program was above average.

Also reviewed were the actions you had taken with respect to the violations observed during our previous inspection conducted on August 26, 1992, and February 10, 1993. The inspection verified that the corrective actions for these violations had been implemented as stated in your reply dated September 28, 1993, and that these actions were effective.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

9404210149 940418
PDR ADOCK 03028835
C PDR

JE07 | 0

Edwards Pipeline Testing, Inc.

-2-

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

Charles L. Cain

Charles L. Cain, Chief
Nuclear Materials Inspection Branch

cc:
Oklahoma Radiation Control Program Director

bcc:
DMB - Original (IE-07)
LJCallan
SJCcollins
RAScarano, DRSS/RIV
MMessier, OC/LFDCB (4503)
*WLFisher
*CLCain
*RABrown
*NMIB
*MIS System
*RIV Files (2)

*W/IFS Form

RIV:NMIB	C:NMIB			
RABrown	CLCain			
04/15/94	04/18/94			

bcc:

DM3 - Original (IE-07)

LJCallan

SJCollins

RAScarano, DRSS/RIV

MMessier, OC/LFDCB (4503)

*WLFisher

*CLCain

*RABrown

*NMIB

*MIS System

*RIV Files (2)

*W/IFS Form

RIV:NMIB <i>RAB</i>	C:NMIB <i>die</i>			
RABrown <i>RAB</i>	CLCain			
04/5/94	04/18/94			