



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

TELEPHONE
AREA CODE 716 546-2700

October 4, 1982

Mr. Ronald C. Haynes, Regional Administrator
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, PA 19406

Subject: LER 82-022/01T, Steam Generator Tube Degradation

Dear Mr. Haynes:

This letter is to confirm our conversation of Friday, October 1, 1982 reporting Licensee Event Report, LER 82-022/01T to your Senior Resident Inspector.

The results of the Eddy Current examination of the "A" Steam Generator inlet (hot leg) indicated one (1) tube with a crevice intergranular attack indication above the plugging limit.

The results of the Eddy Current examination of the "B" Steam Generator inlet indicated the following crevice intergranular attack indications;

- a. Twenty eight (28) tubes in the hot leg with indications above the plugging criteria.
- b. Two (2) tubes in the hot leg with stress corrosion cracking indications of 27%.
- c. Two (2) tubes in the hot leg with absolute signals of significant enough magnitude to indicate corrective action is prudent.

Further information regarding corrective actions for the one (1) tube in the "A" Steam Generator and the thirty two (32) tubes in the "B" Steam Generator, will be presented in our 14 day written report, LER 82-022/01T.

Bruce A. Snow
Bruce A. Snow
Plant Superintendent

xc: J. E. Maier
R. P. Zimmerman
CAR 1404 File

8210190703 821004
PDR ADOCK 05000244
S PDR

IER