

**BOSTON EDISON COMPANY**  
GENERAL OFFICES 800 BOYLSTON STREET  
BOSTON, MASSACHUSETTS 02199

**A. V. MORISI**  
MANAGER  
NUCLEAR OPERATIONS SUPPORT DEPARTMENT

October 7, 1982

BECo. Ltr. #82-266

Mr. Ronald C. Haynes, Director  
Office of Inspection and Enforcement  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA. 19406

License No. DPR-35  
Docket No. 50-293

Subject: IE Bulletin 80-06

Reference (A): Boston Edison Letter dated  
June 27, 1980 from Mr. G. Carl  
Andognini to Mr. Boyce H. Grier

(B): LER 82-025/01T-0

Dear Sir:

In the second response contained in Reference (A), Boston Edison committed to complete IE Bulletin 80-06 related surveillance testing prior to start-up from Refueling Outage #5 (RFO 5). At start-up from RFO 5 we believed this commitment had been fully satisfied.

However, after Pilgrim returned to service an additional review was conducted to ensure the adequacy and completeness of the Bulletin 80-06 tests. This review determined that a modified station surveillance procedure, Temporary Procedure 81-64, PCIS Valve Testing (TP81-64) had the following inadequacies: (1) it inadvertently overlooked the testing of the H<sub>2</sub> Analyzer Isolation Valves; (2) it did not identify the individual Standby Gas Treatment System Isolation Valves; (3) it incorrectly indicated that the O<sub>2</sub> Analyzer Valves are closed after reset, when the valves are actually open.

To correct the identified inadequacies, the Operations Review Committee approved two new temporary procedures, TP82-38, Balance of Plant Isolation "A" and TP82-39, Balance of Plant Isolation "B". During the unscheduled shutdown commencing August 13, 1982, the additional testing was conducted. This testing revealed that wiring to the H<sub>2</sub> Analyzer valves was incorrect. We developed and implemented corrective actions, developed appropriate new test procedures and conducted a test of the logic. The logic tested consistent with its wiring schemes, satisfactorily concluding this test. LER 82-025/01T-0 has been issued to satisfy reporting requirements.

8210190721 821007  
PDR ADOCK 05000293  
PDR  
Q

IE 11

BOSTON EDISON COMPANY

Mr. Ronald C. Haynes, Director  
October 7, 1982  
Page 2

We believe the actions contained in this submittal satisfactorily address the issue; should you wish further information after reviewing it, please contact us.

Very truly yours,

*Amoisi*