

APPENDIX A

NOTICE OF VIOLATION

Southern California Edison Company
San Onofre Units 2 and 3

Dockets: 50-361; 50-362
Licenses: NPF-10; NPF-15

During an NRC inspection conducted on February 1 through March 7, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

10 CFR 73.21(c) and 10 CFR Part 73, Appendix G, Part II, requires recording of safeguards events in a log within 24 hours of discovery of: (1) any failure in a safeguards system that could allow unauthorized or undetected access to a protected area or vital area for which compensatory measures have not been employed; and (2) any other . . . committed act not previously defined in Appendix G with potential for reducing the effectiveness of the safeguards system.

Contrary to the above, on February 2, 1994, the licensee failed to log, within 24 hours of discovery, an event in which a tamper alarm on the entrance to a vital area did not annunciate when the vital area portal was removed.

This is a Severity Level IV violation. (Supplement III)

Dated at Arlington, Texas,
this *15th* day of *April* 1994