

OCT 5 1982

APPENDIX A

NOTICE OF VIOLATION

Groover, Christie & Merritt Associates
Washington, D.C. 20010

Docket No. 30-18996
License No. 08-19624-01

As a result of the inspection conducted on August 20, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

- A. 10 CFR 19.12 requires that all individuals working in restricted areas be instructed in the applicable provisions of the Commission's regulations and licenses.

Contrary to the above, as of August 20, 1982, individuals who were working in the restricted area had not been instructed in the applicable provisions of the regulations and the conditions of the license.

This is a Severity Level IV violation (Supplement VI).

- B. Condition 14 of License No. 08-19624-01 requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in an application dated December 30, 1980.

1. Item 10.A of this application requires that survey instruments be calibrated in accordance with the procedures in Appendix D, Section 1, of Regulatory Guide 10.8, Revision 1. Item A.3 of Appendix D, Section 1 requires that survey meters be calibrated at least annually and after servicing.

Contrary to the above, as of August 20, 1982, the survey meter had not been calibrated since April 1980, a period of more than one year.

This is a Severity Level IV violation (Supplement VI).

2. Item No. 10.B of this application requires that dose calibrators be calibrated in accordance with procedures contained in Appendix D, Section 2, Regulatory Guide 10.8.

Contrary to the above, as of August 20, 1982, the dose calibrator had not been calibrated, and no tests of instrument linearity had been performed since April 1980, a period of greater than one year.

This is a Severity Level IV violation (Supplement VI).

3. Item 11.D of this application requires that surveys be made of unrestricted areas to determine radiation levels.

Contrary to the above, as of August 20, 1982, surveys in the unrestricted corridor adjacent to the Hot Lab preparation area had not been performed since April 1981.

This is a Severity Level IV violation (Supplement VI).

4. Item 15 of this application requires that radioactive material be handled in accordance with Appendix G of Regulatory Guide 10.8.

Item 2 of Appendix G requires that disposable gloves be worn at all times while handling radioactive materials.

Contrary to the above, on August 20, 1982, personnel in the Nuclear Medicine Department failed to wear disposable gloves while handling radioactive materials.

This is a Severity Level IV violation (Supplement VI).

5. Item 17 of this application requires that surveys be performed in accordance with the "Area Survey Procedures" contained in Appendix I of Regulatory Guide 10.8.

Item 5 of Appendix I requires a permanent record of survey results.

Contrary to the above, as of August 20, 1982, a record had not been kept of weekly wipe tests.

This is a Severity Level V violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Groover, Christie & Merritt Associates is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.