## UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

## ATOMIC SAFETY AND LICENSING BOARD

DOCKETED

Administrative Judges:

James Gleason, Chairman Dr. Oscar H. Paris Frederick J. Shon \*82 OCT 18 A11:54

In the Matter of

CONSOLIDATED EDISON COMPANY OF NEW YORK (Indian Point, Unit 2)

Docket Nos. 50-247-SP 50-236-SP

POWER AUTHORITY OF THE STATE OF NEW YORK (Indian Point, Unit 3)

October 13, 1982

WEST BRANCH CONSERVATION ASSOCIATION'S REPLY TO MEMORANDUM AND ORDER OF OCTOBER 1, 1982

Pursuant to page 15 in above described document
West Branch Conservation Association (WBCA) states below
the "threshold finding" in order to retain as a contention
2.2(d).

We do not agree with the statement on page 24, lines I through 3, that finding facts and making remedies after an event is sufficient. WBCA's recommendations are aimed toward further safety by attempting to anticipate problems. The Director's Order is a compilation of remedies, all of the errors that led to the flood in unit #2 are now after the fact. No method has been set to prevent a different, and possibly a same magnitude, event.

The leaks, the faulty water level controls need not have been unknown. On the basis of that event we contend

for WEST BRANCH CONSERVATION ASSOCIATION, INC.

443 Buena Vista Road New City, N.Y. 10956

914/534-2327

Expriral S. Fleisher

by Zipporah S. Fleisher Secretary there is a possibility of similar but undetected faults, which might be detected by an inspection program which does not only respond to crises.

A sophisticated tracing of circuits and systems should be instituted at both units. Such a program would improve the level of safety as called for in Question 2. The corrected measures taken could also be further band-aids. And should a similar failure be lurking it represents a significant risk. To our knowledge, and from past performance, the NRC has no program to reinspect all systems including those which are not safety related. (Sump pumps were not considered safety related until after the flood.)

The fan coolers were supposed to last for the life of the plant - we are trying to avoid future breakdowns, not just addressing what has already been repaired. In order to institute such a program WBCA contends that the record should show that attempts are being made to avoid what might appear to be common mode failures but which can build up into a calamity.

Con Ed was fined \$210,000 for doing something wrong. Examples are: sump pump float control - the rod had no guide at the bottom and jammed. It had hung up and jammed previously. Part of the trouble with leaks had to do with breaks in the cement lining of certain pipes, and which was known and predictable. The containment floor pitched the wrong way allowing water to jump the curbs. Water

level indicators were not properly calibrated. There were no external indicators of the pumping operation. The whole series of events led up to the flooding of the reactor pit and is an indication of a low level of quality control and construction.

The two pronged requirement on page 2 of the Order of October 1, subsection II. A (3) (a) and (b) could be met by a complete inspection and ensuing program of continuing inspection.

Safety would be enhanced and perhaps unit #2 would not be repaired with epoxy patches that went undetected, again. Nor would wiring of the pumps be on the wrong side of the fuses.

#### CONTENTIONS UNDER #5

We need a clarification of how Question 5 will be handled. What is the standing of an intervenor under your description on page 31? Also under Contention 2.2.1?

We received the October 1 Order, postmarked October 4, on October 8. In order to reply to an in-hand date of October 15 we are not addressing questions put to us about contention 5.1 due to time constraints and awaiting disposition of above request regarding the status of Contention 2.2(d).

### UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

# ATOMIC SAFETY AND LICENSING BOARD

DOCKETED HISHRO

Before Administrative Judges:

James Gleason, Chairman Frederick J. Shon

OCT 18 A11:54

In the Matter of-

Dr. Oscar H. Paris

LOUTE HIGH SENV

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC. (Indian Point, Unit No. 2)

Docket Nos. 50-247-SP 50-286-SP October 13,1982

POWER AUTHORITY OF THE STATE OF NEW YORK, (Indian Point, Unit No. 3)

#### CERTIFICATE OF SERVICE

This is to certify that I have this day placed in the first class U. S. mail a copy of the REPLY TO MEMORANDUM AND ORDER OF OCTOBER 1, 1982 to those parties listed below.

Docketing and Service Branch Office of the Secretary U.S. Nuclear Regulatory Commission Washington, DC 20353

Janice E. Moore, Esq. Henry J. McGurren, Esq. NRC Statf Coursei Office of the Executive Legal Director
U.S. Nuclear Regulatory Commission
Vashington, DC 20353

Dr. Oscar H. Paris Administrative Judge Atomic Safety and Licensing Board
U.S. Nuclear Regulatory Commission
Fashington, DC 20555

Mr. Frederick J. Shon Administrative Judge Atomic Salety and Licensing Soard U.S. Nuclear Regulatory Commission Washington, DC 20555

Jeffrey M. Blum, Esq. ew York University Law School -123 Yanderbuit Hall 40 Washington Square South Here York, NY 10012

Phalf Levisoff Standar, Padistrial Emergency Processions troughture State Flata Hor Fullding De 1981 Damis New York (22)

Brent L. Brandenburg, Esq. Assistant General Coursel Consolidated Edison Company of New York, Inc. 4 Irving Place New York, NY 10003

Paul F. Colarulli, E -Joseph J. Levin, Jr., Laq. Pamela S. Horowitz, Esq. Morgan Associates, Chartered 1377 L Street, N.W. Washington, DC 20036

Charles M. Pratt, Esq. Thomas R. Frey, Esq. Power Authority of the State of New York 10 Columbus Circle New York, NY 10019

Ellyn R. Veis, Esq. Villiam S. Jordan, III, Esq. Harmon & Veiss 1723 1 Street, N. V., Suite 306 Veshington, DC 20006

oun Hait, Project Director Joan Half, Project Director
Indian Point Project
New York Public Interest Research Group
Y MU 1712. 4 JT:
New York, NY 10067

Greater New York Council on Energy c/e Dean R. Corren, Director New York University 26 Stuyyesant Street New York, NY 10003

Atomic Safety and Licensing Board Panel U.S. Nuclear Regulatory Commission Weshington, DC 20555 \*\* ASL Appeal Board ASL Appeal Board Panel New City, NY 10956 Pat Poener, Spokesperson Parents Concerned About Indian Point P. O. Box 125 Croton-on-Hudson, NY 10320

Charles J. Maikish, Esq. Litigation Division Port Authority of New York and New Jersey One World Trade Center New York, NY 10044

Alfed B. Desdello Vestchester County Executive Vestchester County 148 Martine Avenue White Plains, NY 10601

Ezra L Blatik, Esq. Steve Leipsiz, Esq. Environmental Protection Bureau New York State Attorney General Two World Trade Center New York, NY 10047

Renew Schwartz, Esc. Botein, Hays, Sciar & Herzberg Attorneys for Metropolitan Transportation Auth 200 Park Avenue New York, NY 101066

Stanley B. Klimbers General Coursel New York State Energy Office Agency Building #2 Emoure State Plaza Albeny, NY 12223

Andrew 5. Roffe, Esq.

Honorable Ruth Messinger

Memoer of the Council of the City of New York

Albany, N.Y. 12248

Distract as City Hall New York, NY 10007

Marc L. Parts. Esq. , Eric Thorsen, Esq. County of Roculand
11 New Hempstead Road

Joan Miles HAW Thre City Auction Society 71 Vest 23re Street, Suite 1325 New York, NY 10010

Charles A. Scheiner, Co-Chairperson Vestcherter People's Action Coalition, Inc. F. O. Box 444 Thite Plains NY 10602

Lorna Salzman Mid-Atlantic Representat Friends of the Earth, Inc. 201 West 13th Street PTERLIVE New York, NY 10011

Judith Kessler Rockland Citizens for Safe Energy P. O. Box 78 New City, NY 10956

Village of Bucha Buchann, NY 10511 Won. Richard Brodsky County Legislature County Office Building White Flains, E.Y. 10601

David H. Pikus, Esq., Richard Czaja, Ta-330 Madison Avenue New York, N.Y. 10017

Plinefre C. Willer, Esc. Albrid Safety and Licensing Scarc Fanel U.S. Suclear Esculator, Commission Massington, C.C. 20888

for West Branch Conservation Association 443 Buena Vista Road, New City, N.Y. 10956 914/634-2327 Pepperan S. Miller

by Zipporah S. Fleisher Secretary