passan and a surround a surround a surround a surround be as a surround a surround be as a surround a surround		and the second	· · ·
NP#C Form-891 ************************************			U.S. NUCLEAR REGULATORY COMMISSION
10 CFR'2.201 -	SAFETY I	NSPECTION	
1. LICENSEE		2. REGIONAL O	
CARGILL, INC. 2306 ROCHESTER AVE.		U.S. NUCLEAR REGULATORY COMMISSION REGION III	
2306 ROCHESTER AVE		799 ROOSEVELT ROAD	
KANSAS CITY, MO 64	120	GLEN ELL	YN, IL 60137
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S		5. DATE OF INSPECTION
030-30134	24-2581	7-01	OCT. 30- NOV. 15, 1990
Licensee:			
Regulatory Commissions (NRC) rules and regulat and representative records, interviews, with perso	ions and the conditions of yo nnel, and observations by the ations were observed	ur license. The inst inspector. The fin	o radiation safety and to compliance with the Nuclear pection consisted of selective examinations of procedures dings as a result of this inspection are as follows: ing the last inspection. We have no further questions on
3. During this inspection certain of your activ THIS IS A NOTICE OF VIOLATION whi			
A			was not properly posted to indicate the presence
of a			
B. Containers located in			
labeled to indicate the presence of radio			
C	1		of sealed sources were not performed at the proper
trequencias. TO CER	an a	Lice	inse Condition Number
D. Records of			were not properly maintained.
10 CFR	******	or License Conditio	on Number
E. Documents were not properly posted o	r otherwise made available. 1	0 CFR 19.11.	
F. Reports or notifications of			were not made in accordance
with 10 CFR		or License Conditio	on Number
Пн			
[] I,			
	and the second second second second second		
J			
Ск 9012110 REG3 LI 24-2581	206 901130 C30 7-01 PDC		
			rrect the violations identified in the items checked above. . No further response will be submitted unless requi- by
This statement of corrective actions is made in acc			