

NOTICE OF VIOLATION

Marquette University
Milwaukee, Wisconsin

License No. 48-02931-06
Docket No. 030-01154

As a result of the inspection conducted on October 24, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, (1990) (Enforcement Policy) the following violations were identified:

1. 10 CFR 19.11(a) and (b) require, in part, that the licensee post current copies of Part 19, Part 20, the license, license conditions, documents incorporated into the license, license amendments and operating procedures; or that the licensee post a notice describing these documents and where they may be examined. 10 CFR 19.11(c) requires that a licensee post Form NRC-3, "Notice to Employees."

Contrary to the above, on October 24, 1990, required documents or notices were not posted in four of the six laboratories toured by the inspector.

This is a Severity Level V violation (Supplement VI).

2. License Condition No. 15 requires the licensee to maintain a record of physical inventories conducted every six months to account for all foil sources possessed.

Contrary to the above, records of physical inventories of foil sources conducted in 1990 were not maintained.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

NOV 28 1990

Dated _____

William H. Schultz
William H. Schultz, Chief
Nuclear Materials Safety
Section 1

9012110293 901128
REG3 LIC30
48-02931-06 PDC