UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064 APR 20 1994 Dockets: 030-12750 030-15184 Licenses: 35-03176-04MD

35-03176-05

The University of Oklahoma Health Sciences Center ATTN: Dr. J. H. Stein Senior Vice President and Provost

P. G. Box 26901

Oklahoma City, Oklahoma 73190

SUBJECT: NRC INSPECTION REPORT 030-12750/94-01: 030-15184/94-01

This refers to the routine, unannounced inspection conducted by Mr. Gilbert L. Guerra, Jr., of this office on April 11-13, 1994. The inspection included a review of activities authorized by Byproduct Materials Licenses 35-03176-04MD and 35-03176-05. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector noted that the radiation safety office had continued to implement its aggressive audit program for activities conducted under these two licenses. As is evident by the results of this inspection, such an auditing program is beneficial in maintaining licensed activities in compliance.

While observing activities in the nuclear pharmacy the inspector noted that daily operations such as order receipt, dose preparation, quality control checks, and shipment preparation were properly performed and were appropriately documented.

Also, the inspector toured the waste storage and incinerator areas associated with the waste management license. He discussed waste handling procedures with your staff, specifically how decay-in-storage and incineration operations

9404270044 940420 PDR ADOCK 03012750 PDR

200000

have been handled. He concluded that appropriate procedures and controls had been instituted in maintaining effluents and doses as low as reasonably achievable (ALARA).

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

Charles L. Cein

Charles L. Cain, Chief Nuclear Materials Inspection Branch

cc: Oklahoma Radiation Control Program Director bcc:
DMB - Original (IE-07)
LJCallan
SJCollins
RAScarano, DRSS/RIV
MMessier, OC/LFDCB (4503)
*WLFisher
*CLCain
*GLGuerra
*NMIB
*MIS System
*RIV Files (2)

*W/IFS Form

RIV:NMIB	C:NMIBUNC		
GLGuerra	CLCain		
04/19/94	04/20/94		

bcc: DMB - Original (IE-07) LJCallan SJCollins. RAScarano, DRSS/RIV MMessier, OC/LFDCB (4503) *WLFisher *CLCain *GLGuerra *NMIB *MIS System *RIV Files (2)

*W/IFS Form

RIV:NMIB	C:NMIBUVE	
GLGuerra	CLCain	
04/19/94	04/20/94	