



# MISSISSIPPI POWER & LIGHT COMPANY

*Helping Build Mississippi*

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 18, 1982

JAMES P. McGAUGHY, JR.  
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-46  
License No. NPF-13  
File 0260/L-835.0  
Division 2 Standby Diesel  
Generator Rear Crankcase  
Cover Capscrew Defective  
Reference: LER 82-080/01 T-0  
AECM-82/483

With the unit in cold shutdown, a special inspection on the Division 2 Standby Diesel Generator was conducted. During this inspection, one of the capscrews which secures the rear crankcase cover to the engine block was discovered to be defective. This report is being submitted pursuant to T.S.6.9.1.12.e. and i. Attached is LER 82-080/01 T-0 with supplementary information.

Yours truly,

JPM:sap  
Attachment

cc: Mr. N. L. Stampley (w/a)  
Mr. R. B. McGehee (w/o)  
Mr. T. B. Conner (w/o)  
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk (w/a)  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8210220131 821018  
PDR ADOCK 05000416  
S PDR

Member Middle South Utilities System

OFFICIAL COPY

LE 22

82 OCT 19 AID: 03  
REGION II  
ATLANTA, GEORGIA