

Docket Nos. 50-456; 50-457 License Nos. NPF-72; NPF-77 EA 94-068

Commonwealth Edison Company ATTN: Mr. K. Kaup Site Vice President Braidwood Station RR #1, Box 84 Braceville, IL 60407

Dear Mr. Kaup:

This refers to the special inspection conducted by Messrs. S. G. Du Pont and E. R. Duncan of this office on March 7 through April 5, 1994. The inspection included a review of activities authorized for your Braidwood facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, and discussions with personnel.

Based on the results of this inspection, one apparent violation was identified and is being considered for escalated enforcement action in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy), 10 CFR Part 2, Appendix C (1993). The apparent violation involved the failure to have either train of Main Control Room Ventilation operable as required by Technical Specification 3.7.6. Accordingly, no Notice of Violation is presently being issued for these inspection findings. In addition, please be advised that the number and characterization of the apparent violation described in the enclosed inspection report may change as a result of further NRC review.

An enforcement conference to discuss this apparent violation has been scheduled for April 28, 1994. The purposes of this conference are to discuss the apparent violation, its cause and safety significance; to provide you the opportunity to point out any errors in our inspection report; to provide an opportunity for you to present your proposed corrective actions; and to discuss any other information that will help us determine the appropriate enforcement action in accordance with the Enforcement Policy. You will be advised by separate correspondence of the results of our deliberations on this matter. No response regarding the apparent violation is required at this time.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Sincerely,

Original signed by E. C. Creatann

Edward G. Greenman, Director Division of Reactor Projects

Enclosure: Inspection Report No. 50-456/94008(DRP); No. 50-457/94008(DRP)

cc w/enclosure:

L. DelGeorge, Vice President, Nuclear Oversight & Regulatory Services

K. Kofron, Station Manager

K. Bartes, Regulatory Assurance Supervisor

D. Farrar, Nuclear Regulatory Services
Manager

OC/LFDCB

Resident Inspectors, Braidwood, Byron, Zion

H. A. Learner

R. Hubbard

N. Schloss, Economist, Public

Utilities Division

Licensing Project Manager, NRR

State Liaison Officer

Chairman, Illinois Commerce Commission

S. Stein, SRS

J. Goldberg, OGC

J. Lieberman, OE

L. Reyes, NRR

bcc: PUBLIC - IE01

RIII

Landsman

RIII

11

Jorgensen

See Previous Concurrences
RIII RIII

DeFayette

Hadsman

Greenman

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Sincerely,

Edward G. Greenman, Director Division of Reactor Projects

Enclosure: Inspection Report No. 50-456/94008(DRP); No. 50-457/94008(DRP)

cc w/enclosure:

L. DelGeorge, Vice President, Nuclear Oversight & Regulatory Services

K. Kofron, Station Manager

K. Bartes, Regulatory Assurance Supervisor

D. Farrar, Nuclear Regulatory Services Manager

OC/LFDCB

Resident Inspectors, Braidwood, Byron, Zion

H. A. Learner

R. Hubbard

N. Schloss, Economist, Public Utilities Division Licensing Project Manager, NRR State Liaison Officer

Chairman, Illinois Commerce Commission

S. Stein, SRS

bcc: PUBLIC - IE01

RALI Landsman

Jorgensen

PES De Faxette

RIII

RIII

Hausman

Greenman