



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 8, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Smoke Detector Inadvertent
Alarm
Reference: LER 82-067/03 L-0
AECM-82/470

82 OCT 12
AID:
USNRC REGION II
ATLANTA, GEORGIA

On September 10, 1982, the smoke detectors in the Auxiliary Building corridor area (elevation 119 foot) alarmed and would not reset. Investigation revealed no smoke or fumes. The detectors were deactivated, cleaned, adjusted and returned to service. A fire watch was established per T.S.3.3.7.9. Attached is LER 82-067/03 L-0.

Yours truly,

J. P. H. Gaughy
for J. P. H. Gaughy

JPM:sap
Attachment

cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8210220259 821008
PDR ADOCK 05000416
S PDR

OFFICIAL COPY