



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 18, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Fire Detection Zone Trouble
Light - Improperly Seated
Smoke Detector
Reference: LER 82-086/03 L-0
AECM-82/487

82 OCT 19 AID
USNRC REGION II
ATLANTA, GEORGIA

On September 16, 1982, the fire detection zone 2-6 trouble light alarmed and would not clear. An LCO was entered in accordance with T.S.3.3.7.9. This report is being submitted pursuant to T.S.6.9.1.13.b. Attached is LER 82-086/03 L-0.

Yours truly,

JPM:sap
Attachment

- cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8210220269 821018
PDR ADOCK 05000416
S PDR

OFFICIAL COPY

IE 22