

APPENDIX

U. S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-267/90-12

Operating License: DPR-34

Docket: 50-267

Licensee: Public Service Company of Colorado
P. O. Box 840
Denver, Colorado 80201-0840

Facility Name: Fort St. Vrain Nuclear Generating Station (FSV)

Inspection at: FSV, Platteville, Colorado

Inspections Conducted: June 19, July 10 and 31, 1990

Inspectors: Paul W. Michaud 10-22-90
Paul W. Michaud, Project Manager
Uranium Recovery Field Office Date

Pete J. Garcia Jr. 10/22/90
Pete J. Garcia, Jr., Project Manager
Uranium Recovery Field Office Date

Approved: Ramon E. Hall 10/22/90
Ramon E. Hall, Director
Uranium Recovery Field Office Date

Inspection Summary

Inspections Conducted June 19, July 10, and 31, 1990 (Report 50-267/90-12)

Areas Inspected: Routine, announced inspection of the licensee's physical security program. The areas inspected within the physical security program included the physical security program plan, procedures, audits, access control, contingencies, records, and transfers of special nuclear material, testing and maintenance.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

9012120280 901205
PDR ADOCK 05000267
Q PNU

Results: The inspectors observed the licensee's control of access to the transport area and the fuel building during fuel movement activities. The inspectors also observed radiological controls and reviewed the licensee's internal audits of the transportation security program. Within the areas inspected no violations or deviations were identified.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED