

APPENDIX A  
NOTICE OF VIOLATION

Florida Power & Light  
Turkey Point 4

Docket No. 50-251  
License No. DPR-41

As a result of the inspection conducted on June 26 - July 25, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.12.1.b requires that each high radiation area in which the intensity of radiation is greater than 1000 mRem/hr shall be locked to prevent unauthorized entry.

Contrary to the above, on July 1, 1982 at approximately 1315 hours, both ground level gates to the RHR pit stairways on Unit 4 were found open and unattended. Current licensee radiation surveys detected dose rates in the RHR pit stairway area in excess of 1000 mRem/hr.

This is a Severity Level IV Violation (Supplement IV.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

**AUG 26 1982**

Date: \_\_\_\_\_