DUKE POWER COMPANY

P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE (704) 373-4531

October 15, 1982

Mr. James P. O'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1 Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-70. This report concerns T.S.3.3.3.9, "The radioactive gaseous effluent monitoring instrumentation channels shown in Table 3.3-13 shall be operable with their alarm/trip setpoints set to ensure that the limits of Specification 3.11.2.1 are not exceeded". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H.B. Tircher 110

Hal B. Tucker

PBN:jfw Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

Mr. P. R. Bemis Senior Resident Inspector McGuire Nuclear Station Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

