

OCT 18 1982

Docket No. 30-16008

License No. 20-19067-01

Baker Testing Services, Inc.  
ATTN: Mr. Kenneth Baker  
Vice President  
25 Fottler Road  
Hingham, Massachusetts 02043

Gentlemen:

Subject: Inspection No. 30-16008/82-01

This refers to your letter dated September 21, 1982, in response to our letter dated August 23, 1982.


Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

With respect to your answer to Item C, you supplied additional information regarding the calibration of your survey meter. However, it was noted that the date of the calibration was February 2, 1982, which was an interval of more than three months since the latest calibration on July 30, 1982. You should assure that calibrations are completed at intervals not exceeding three months.

Your cooperation with us is appreciated.

Sincerely,

Original Signed  
John D. Kinneman




Thomas T. Martin, Director  
Division of Engineering and  
Technical Programs


cc:


Fred E. Straut, Assistant Radiation Safety Officer  
Public Document Room (PDR)  
Nuclear Safety Information Center (NSIC)  
Commonwealth of Massachusetts (2)

bcc:

Region I Docket Room (with concurrences)

 DETP  
McGinness/lp  
10/8/82

 RI:DETP  
Davis  
10/15/82

 RI:DETP  
Kinneman  
10/15/82

OFFICIAL RECORD COPY

1K:07

8210220423 821018  
NMS LIC30  
20-19067-01 PDR