

December 7, 1990

Docket No. 50-346

Mr. Donald C. Shelton
Vice President, Nuclear
Toledo Edison Company
Edison Plaza - Stop 712
300 Madison Avenue
Toledo, Ohio 43652

Dear Mr. Shelton:

SUBJECT: UNIMPLEMENTED GENERIC SAFETY ISSUES AT DAVIS-BESSE NUCLEAR
POWER STATION, UNIT NO. 1 (DBNPS)

On April 25, 1990, the staff issued Generic Letter 90-04 which requested information concerning the implementation status of certain generic safety issues (GSIs) at your facility. Based on your response to this Generic Letter, dated June 29, 1990, our own records and discussions with your staff, we have updated our database on GSI implementation status. The results of this effort were presented to the Commission at a meeting on October 25, 1990.

With respect to GSI Item 67.3.3 (MPA A017) which relates to improved accident monitoring per Regulatory Guide 1.97, Revision 3, Inspection Report 50-346/90021 was issued on November 21, 1990, and closed all but three of the previously unresolved items. These open items were initially identified as Items -02, -04, and -08 in Inspection Report 50-346/88038.

The enclosure to this letter summarizes the staff's understanding of the current status of those GSIs which remain unimplemented at DBNPS. We appreciate the assistance you provided in responding to Generic Letter 90-04 and we encourage your timely completion of those GSIs listed in the enclosure.

Please contact me if you have any questions or comments about the enclosed information.

Sincerely,

original signed by

M. D. Lynch, Sr. Project Manager
Project Directorate III-3
Division of Reactor Projects - III,
IV, V and Special Projects
Office of Nuclear Reactor Regulation

Enclosure:

A: stated

cc w/enclosure:

See next page

DOCUMENT NAME: UGSI - DAVIS-BESSE

DISTRIBUTION

AHsia	RScholl	DMiller	Docket File	NRC & Local PDRs	DCrutchfield
JZwolinski		PKreutzer		OGC	MDLynch
OGC		EJordan		ACRS	PD33 r/f
PD33 gray		EGreenman(RIII)	BBoger	HBerkow	DDilanni

LA/PDIII-3	PM/PDIII-3	PM/PDIII-3	PD/PDIII-3
PKreutzer	AHsia	MDLynch	JHannon
12/7/90	12/7/90	12/07/90	12/17/90

DF01
11

9012130227 901207
PDR ADOCK 05000346
PDC
P

Mr. Donald C. Shelton
Toledo Edison Company

Davis-Besse Nuclear Power Station
Unit No. 1

cc:

David E. Burke, Esq.
The Cleveland Electric
Illuminating Company
P. O. Box 5000
Cleveland, Ohio 44101

Radiological Health Program
Ohio Department of Health
1224 Kinnear Road
Columbus, Ohio 43212

Mr. Robert W. Schrauder
Manager, Nuclear Licensing
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Attorney General
Department of Attorney
General
30 East Broad Street
Columbus, Ohio 43215

Gerald Charnoff, Esq.
Shaw, Pittman, Potts
and Trowbridge
2300 N Street N.W.
Washington, D.C. 20037

Mr. James W. Harris, Director
(Addressee Only)
Division of Power Generation
Ohio Department of Industrial Relations
2323 West 5th Avenue
P. O. Box 825
Columbus, Ohio 43216

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Ohio Environmental Protection Agency
DERR--Compliance Unit
PO Box 1049
1800 Watermark Drive
ATTN: Zack A. Clayton
Columbus, Ohio 43266-0149

Mr. Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation Division
Suite 525, 1700 Rockville Pike
Rockville, MD 20852

President, Board of
County Commissioners of
Ottawa County
Port Clinton, Ohio 43452

Resident Inspector
U. S. Nuclear Regulatory Commission
5503 N. State Route 2
Oak Harbor, Ohio 43449

State of Ohio
Public Utilities Commission
180 East Broad Street
Columbus, Ohio 43266-0573

UNIMPLEMENTED GSIs AT DAVIS-BESSE NUCLEAR POWER STATION, UNIT NO. 1

<u>GSI/MPA No.</u>	<u>TITLE</u>	<u>PROJECTED IMPLEMENTATION DATE</u>	<u>REMARKS</u>
51/L913	Improving the Reliability of Open-Cycle Service Water Systems	02/92	Actions to im- plement NRC recom- mendations I through IV will be completed by end of 7RFO (2/92).
67.3.3/A017	Improved Accident Monitoring	03/91	Region III reinspec- tion conducted from 10/15/90 to 11/05/90 and Inspection Report 50-346/90021 was issued on 11/21/90. Three items remain unresolved.
59/L817	RCS/RHR Suction Line Valve Interlock on PWRs	12/91	Interlocks to be removed at the end of the current fuel cycle (cycle 7).