




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

October 15, 1982  
RBG- 13,570  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-75

On September 21, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning an error found in the GHOSH computer program used in the reactor building hydrodynamic analysis. GSU has not completed its investigation to determine the significance of the error. An interim or final status report will be provided by January 14, 1983.

Sincerely,

J. E. Booker  
Manager-Engineering & Licensing  
River Bend Nuclear Group

JEB/~~JK~~/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

R. L. Brown (RRI)

IE 27