

Certified By map**PSEG**

Public Service Electric and Gas Company P O Box E Hancock's Bridge New Jersey 08038

Salem Generating Station

October 19, 1982

Mr. R. C. Haynes
 Regional Administrator
 USNRC
 Region 1
 631 Park Avenue
 King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:


REPORTABLE OCCURRENCE 82-122/01P
 SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Headquarters on Monday, October 18, 1982, advising of a potential reportable occurrence in accordance with IE Bulletin 80-24.

During routine power operation, a service water leak was discovered inside the Containment Building, on No. 24 Containment Fan Coil Unit. The leak rate was approximately 0.4 gallons per minute, and the leak has been isolated.

An investigation is in progress, and a detailed report will be submitted in the time period specified by IE Bulletin 80-24.

Sincerely yours,



H. J. Midura
 General Manager -
 Salem Operations

RF:ks

CC: Distribution

8210260335 821019
 PDR ADOCK 05000311
 S PDR

IE29