

The information on this page is considered to be appropriate for public disclosure pursuant to 10 CFR 2.790.

U.S. NUCLEAR REGULATORY COMMISSION

Region V

Report No. 70-1257/82-10 (IE-V-526)
Docket No. 70-1257 License No. SNM-1227 Safeguards Group 1
Licensee: Exxon Nuclear Company, Inc.
777 106th Avenue Northwest
Bellevue, WA. 98004

Facility Name: Exxon Nuclear Fuel Fabrication Facility
Inspection at: Horn Rapids Site, Richland, WA

Inspection Conducted: September 20-24, 1982

Date of Last Material Control and Accounting Inspection Visit: August 2-6, 9-13, 1982

Type of Inspection: Unannounced, Material Control and Accounting

Inspectors: *A. V. Wieder* 10/18/82
A. V. Wieder, Safeguards Auditor Date Signed

Date Signed

Date Signed

Approved by: *L. R. Norderhaug* 10/18/82
L. R. Norderhaug, Chief, Safeguards Branch Date Signed

Inspection Summary:

Areas Inspected: Routine safeguards inspection following up on closing out the Notice of Deviation, performing a records and reports audit and independent inspection. This inspection included 31 man-hours on-site by one NRC inspector.

Results: No items of noncompliance were identified in the areas inspected.

8210260402 821018
PDR ADDCK 07001257
C PDR