

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

92 OCT 18
AID: 08
NRC REGION
ATLANTA, GEORGIA

October 13, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/82023 - REVISION 2

The enclosed report is a supplement to my letters to you dated April 20, 1982
and June 17, 1982 concerning "A" recirculation pump tripping because of operation
of the generator stator temperature relay. This report is submitted in
accordance with Browns Ferry unit 1 Technical Specification 6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8210290054 821013
PDR ADDCK 05000259
S PDR

OFFICIAL COPY

IE 22