Replaces

syncor

December 3, 1990

Mr. William H. Schultz, Chief Nuclear Materials Safety Section 1 U.S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Re: Docket No.: 030-10975 License No.: 34-16405-01MD

Dear Mr. Schultz:

Following is our reply and the corrective actions taken as a result of the violations identified during the routine safety inspection conducted on October 2 and 4, 1990.

Violation 1. Surveys

Surveys of all elution, preparation, assay and dispensing areas are being performed on Sunday when emergency call requires radioactive material to be handled on Sundays. The results achieved are: no surveys have been missed when required to be performed.

Full compliance was achieved October 5, 1990.

Violation 2. Dose Calibrator Accuracy Checks

An accuracy check has be performed on all dose calibrators being actively used at this location.

To avoid further violations of this type a date for performing this check will be placed into a computer tickler file to incure that this check is performed at a minimum annually and Barium 133 will be measured along with the other standards at that time.

Full compliance was achieved December 3, 1990.

Sincerely,

Frank R. alte RPh.

Frank R. Alto, R.Ph. Radiation Safety Officer

cc: License file



Innovators in high-tech pharmacy services

IE07



Mr. Eill Reichold Muclear Regulatory Commission 794 Roosevelt Road

Dear Billi

As per our conversation on Thursday, October 18, 1990, we have decided to label our hits with only the expiration times.

Suncerely,

Frank R. alto R.Ph.

Manager Cleveland Syncor

cci. Frank Cower Randy Ashus Curt Black Steve Shipper



Innovators in high-tech pharmacy services