LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	G A E I H 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 6 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 3 2 1 7 0 9 1 5 8 2 8 1 0 1 4 8 2 9 SOURCE 60 31 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	With Unit 1 operating steady state at 2236 MWt, a Quality Control (QC)
0 3	review disclosed the installation of a non-"Q" part in the level switch
0 4	on the "A" loop core spray discharge line. The health and safety of
0 5	the public were not affected by this non-repetitive event.
0 6	
0 7	
7 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	CODE SUBCODE S
	17 REPORT NUMBER 2 23 24 26 27 28 29 30 31 32 REVISION NO.
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER H 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 43 25 Z 9 9 9 9 26
10	The cause of this event was ineffective administrative procedures. The
111	part was ordered on a non-"Q" purchase order. An enginer ing review by
1 2	Bechtel stated that the required "Q" functions were not affected by the
1 3	changed switch. An investigation is in progress.
1 4	9 80
	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 A 31 QC AUDIT
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA NA NA
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 NA
1 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA
1 9	So to the damage to facility (43) Type Description NA NA
2 0	9 10 PUBLICITY 15SUED DESCRIPTION (45) NA S PDR NRC USE ONLY NRC USE ONLY PDR NRC USE ONLY S PDR
7 8	9 10 68 69 80 5 NAME OF PREPARER S. B. TIPPS PHONE: (912) 367-7851 0