2nd respons

THE CINCINNATI GAS & ELECTRIC COMPANY



September 30, 1982 OA-2022

E. A. BORGMANN

U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Attention: Mr. J. G. Keppler Regional Administrator

RE: WM. H. ZIMMER NUCLEAR POWER STATION UNIT 1
I.E. INSPECTION REPORT NO. 81-27, ITEM 2,
PIPE LUG ATTACHMENTS, DOCKET NO. 50-358,
CONSTRUCTION PERMIT NO. CPPR-88
W.O. #57300, JOB E-5590, FILE NO. NRC-1

Gentlemen:

This letter constitutes a follow-up to our previous response, QA-1929, dated August 24, 1982 regarding Item 2 of the subject Inspection Report.

In the previous response, CG&E stated that all pipe lugs, similar to the one identified by the Commission in the subject report, would be penetrant examined. There are thirty-four (34) such lugs in piping systems, of which twelve are in process. The remaining twenty-two (22) completed welds have been dye penetrant inspected with twenty (20) identified as having indications which have been documented on Nonconformance Reports.

A follow-up report will be submitted by November 30, 1982 to describe the necessary corrective actions required to resolve this concern.

We trust the above will be found acceptable as a follow-up report concerning the subject deficiency.

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

Ву

E. A. BORGMANN

SENIOR VICE PRESIDENT

FKP:plc

cc: NRC Office of Inspection & Enforcement
Washington, D.C. 20555
NRC Senior Resident Inspector
Attn: W. F. Christianson
Zimmer Project Inspector
Region III

8210290281 821026 PDR ADDCK 05000358 Q PDR