

LICENSEE EVENT REPORT

U. S. NUCLEAR REGULATORY COMMISSION  
UPDATE REPORT - PREVIOUS  
REPORT DATE - 7/27/82

CONTROL BLOCK: [ ][ ][ ][ ][ ][ ][ ][ ][ ][ ][ ][ ] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1][G][A][E][I][H][1] (2) [0][0][0][0][0][0][0][0][0][0] - [0][0][0][0] (3) [4][1][1][1][1] (4) [ ][ ][ ][ ][ ][ ][ ][ ][ ][ ][ ][ ] (5)  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT  
[0][1] REPORT SOURCE [L] (6) [0][5][0][0][0][3][2][1] (7) [0][6][2][8][8][2] (8) [1][0][1][2][8][2] (9)  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] | On June 28, 1982, Unit 1 was in operation at 100% power and the "C" RHR |  
[0][3] | Service Water Pump failed to pass the requirements of the "RHR Service |  
[0][4] | Water Pump Operability and Rated Flow" procedure. The redundant |  
[0][5] | systems were operable. Plant operation was not affected. Public health |  
[0][6] | and safety were not affected by this non-repetitive event. |  
[0][7] | |  
[0][8] | |

[0][9] SYSTEM CODE [C][F] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [B] (13) COMPONENT CODE [P][U][M][P][X][X] (14) COMP. SUBCODE [B] (15) VALVE SUBCODE [Z] (16)  
7 8 9 10 11 12 13 18 19 20  
[17] LER/RO REPORT NUMBER [8][2] (17) EVENT YEAR [8][2] (21) SEQUENTIAL REPORT NO. [0][5][4] (24) OCCURRENCE CODE [0][3] (28) REPORT TYPE [X] (30) REVISION NO. [1] (32)  
ACTION TAKEN [D] (18) FUTURE ACTION [Z] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0][0][0][0] (22) ATTACHMENT SUBMITTED [Y] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [A] (25) COMPONENT MANUFACTURER [J][1][0][5] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] | The cause of the "C" RHRSW pump failing to meet rated flow requirements |  
[1][1] | was due to normal wear on the impeller seal rings and on the casing |  
[1][2] | wear rings. The pump was removed, rebuilt, installed and successfully |  
[1][3] | retested on July 9, 1982. |  
[1][4] | |

[1][5] FACILITY STATUS [E] (28) % POWER [1][0][0] (29) OTHER STATUS [NA] (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION [Inservice inspection/surveillance] (32)  
7 8 9 10 12 13 44 45 46 80  
[1][6] ACTIVITY CONTENT RELEASED OF RELEASE [Z] (33) [Z] (34) AMOUNT OF ACTIVITY [NA] (35) LOCATION OF RELEASE [NA] (36)  
7 8 9 10 11 44 45 80  
[1][7] PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION [NA] (39)  
7 8 9 11 12 13 80  
[1][8] PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION [NA] (41)  
7 8 9 11 12 80  
[1][9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [NA] (43)  
7 8 9 10 80  
[2][0] PUBLICITY ISSUED DESCRIPTION [N] (44) DESCRIPTION [NA] (45)  
7 8 9 10 80

8210290375 821012  
PDR ADOCK 05000321  
S PDR

NRC USE ONLY