## DEC 1 0 1990

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald C. Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

## Gentlemen:

This refers to the routine safety inspection conducted by Messrs. P. M. Byron, and R. K. Walton of this office on October 10, 1990, through November 26, 1990, of activities at Davis-Besse Nuclear Power Station authorized by Facility Operating License No. NPF-3 and to the discussion of our findings with Mr. L. Storz at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No :iolations of NRC requirements were iden ified during the course of this inspection

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

kichard C. Knop, Chief

Division of Reactor Projects

RC Knop

Inclosure: Inspection Report
No. 50-346/90020(DRP)

See Attached Distribution

9012200021 901210 FDR ADDCK 05000346 Q PDR

RIII

A or

Dunlop/pb

12-10-9

RIII Lofo Jackiw 12-10-40 RIII Amo Greger 12/10/90 RIII ACK Knop 12/10/90

1001

## Distribution:

cc w/enclosure:
L. Storz, Plant Manager
DCD/DCB (RIDS)
\*Licensing Fee Management Branch
Resident Inspector, RIII
James W. Harris, State of Ohio
Robert E. Owen, Ohio
Department of Health
A. Grandjean, State of Ohio,
Public Utilities Commission