



**Commonwealth Edison**

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

August 24, 1982

DJS Ltr. #82-902

James G. Keppler, Regional Administrator  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

This letter is being submitted to your office to delete Reportable Occurrence Report #82-28/03L-0, Docket #050-237. The original report is being reclassified as a non-reportable occurrence because the Isolation Condenser Valve MO-1301-10 failed in the open position, or operating position. Therefore, the Isolation Condenser was not operated in a degraded mode and was not in violation of T.S. 6.6.B.2.b.

D. J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

8211010153 820824  
PDR ADOCK 05000237  
S PDR

OCT 4 1982

IE 22