SAFEGUARDS INFORMATION



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30323

Report Nos.: 50-259/90-3 30 160/90-34, and 50-296/90-34

Licensee: Tennessee Valley Authority

38A Lookout Place

f anooga, TN 37402-2801

Docket Nos.: ±0-259, 50-260 and 50-296 License Nos.: DPR-33, DPR-52,

and DPR+68

Facility Name: Browns Ferry 1, 2, and 3

Inspection Conducted: October 29 - November 2, 1990

Inspectors:

Orysia M. Masayk, Safeguards Specialist

Date Signed

avid H. Thompson, Safeguards Specialist

12-5-90 Date Signed

Aubrey, Th Tman, Safeguards Specialist

Date Signed

Approved by

David R. McGuire, Chief

Safeguards Section

Radiation Safety and Safeguards Branch Division of Radiation Safety and Safeguards Date Silgned

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the areas of Physical Security P \neg gram for Power Reactors. Also the improvement issues tracked by NUREG-1232 were reviewed.

Results:

In the areas inspected, three violations of regulatory requirements were identified:

- Inadequate alarm capability.

- Cracked bullet resistant glass.

- Inadequate access control search equipment.

Additionally, one unresolved item in the area of alarm module function in the alarm stations was identified.