



**LOUISIANA
POWER & LIGHT**


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

October 21, 1982

L. V. MAURIN
Vice President
Nuclear Operations

W3182-0079
Q-3-A35.07.57

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 57
"Inadequate Instrumentation and Control
Installations and Turnover Documentation"
Second Interim Report

REFERENCE: LP&L Letter W3K-82-0520 dated August 17, 1982

Dear Mr. Collins:

At the present time, Mercury and Ebasco have formed several "Joint Walk Down" teams representing Mercury Engineering, Mercury QC, and Ebasco Construction Engineering. By this method all existing conditions requiring engineering evaluation, corrective action or rework have been identified. Further information concerning the progress of this effort will be supplied by April 4, 1983.

Very truly yours,

L. V. Maurin

LVM/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 2)