




ARKANSAS POWER & LIGHT COMPANY  
 POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 15, 1982



ØCANØ982Ø2

Mr. John T. Collins  
 Regional Administrator  
 U. S. Nuclear Regulatory Commission  
 Region IV  
 611 Ryan Plaza Drive, Suite 1000  
 Arlington, TX 76011

Subject: Arkansas Nuclear One - Units 1 & 2  
 Docket Nos. 50-313 and 50-368  
 License Nos. DPR-51 and NPF-6  
 Clarification of IE Bulletin 82-01  
Rev. 1, Supplement 1

Gentlemen:

On September 8, 1982, Mr. Jan Kozyra of my staff contacted Joe Collins, NRC-Headquarters, to obtain clarification of certain aspects of IE Bulletin 82-01 Revision 1, Supplement 1. As a result of their conversation we have the following understanding of the points of the Bulletin: (1) The Bulletin requires a 100 percent review of radiograph sets representing welds associated with pipe wall thickness less than ½-inch in shop fabricated quality Class 1 and 2 subassemblies provided by ITT dating back to our initial purchases of such items. (2) IE Bulletin 82-01, Revision 1, Supplement 1 applies only to ANO-2. (3) The Bulletin is not intended to require 100 percent reinterpretation of welds, but rather to identify alterations to radiographs and to require appropriate remedial action.

Very truly yours,

*Donald A. Ruster*  
 for John R. Marshall  
 Manager, Licensing

JRM/JK/rd

8211020117 820915  
 PDR ADOCK 05000313  
 PDR  
 9

IE31