

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

April 2, 1981

TELEPHONE AREA 704
373-4000

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-25. This report concerns seismic qualification for several cable tray hangers in the Unit 1 Reactor Building. This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

William O. Parker Jr. by W.A.H.
William O. Parker, Jr.

RWO:scs

Attachment

cc/ Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
P. O. Box 10412
Palo Alto, California 94303

1E22
BACKETT
ADD:
M Collins
LA-1210
L E
11