#### OPERATING DATA REPORT

DOCKET NO. 50-333

DATE September, 1981

COMPLETED BY F. Zufelt
TELEPHONE (315) 342-3840

OPERATING STATUS		[N	
1. Unit Name: FITZPATRIC	CK	Notes	
2. Reporting Period: 810801-810		The second second	
3. Licensed Thermal Power (MWt):	2436		
4. Nameplate Rating (Gross MWe):	883		
5. Design Electrical Rating (Net MWe):	821		
6. Maximum Dependable Capacity (Gross M	(We): 830		
7. Maximum Dependable Capacity (Net MW			
8. If Changes Occur in Capacity Ratings (Ite	ems Number 3 Through 7) Si	nce Last Report, Give R	easons:
o. If Changes occur in capacity rannings (	NONE		
	NONE		
9. Power Level To Which Restricted, If Any	(Net MWe):		
10. Reasons For Restrictions, If Any:			
	This Month	Yrto-Date	Cumulative
	744	5831	53448
11. Hours In Reporting Period	553.8	5192.7	38106.7
2 Number Of Hours Reactor Was Critical	0	0	0
3. Reactor Reserve Shutdown Hours	521.2	5098.5	37001.3
4. Hours Generator On-Line	0	0	0
5. Unit Reserve Shutdown Hours	1068768	11759664	75943258
6. Gross Thermal Energy Generated (MWH)	266070	4062820	25892330
7. Gross Electrical Energy Generated (MWH)	354460	3938150	25063230
8. Net Electrical Energy Generated (MWH) 9. Unit Service Factor	70.1%	87.4%	69.2%
O. Unit Availability Factor	70.1%	87.4%	69.2%
1. Unit Capacity Factor (Using MDC Net)	58.8%	83.4%	62.9%
2. Unit Capacity Factor (Using DER Net)	58.0%	82.3%	57.1%
3. Unit Forced Outage Rate	29.9%	12.6%	17.5%
4. Shutdowns Scheduled Over Next 6 Month		of Each):	
Refueling and maintenanc	e outage schedul	ed to commence	e in October
Duration is presently pl			
buration is presently pr	anned for the da	30.	
5. If Shut Down At End Of Report Period, E			A a b Second
26. Units In Test Status (Prior to Commercial	Operation):	Forecast	Achieved
INITIAL CRITICALITY	1		
INITIAL ELECTRICITY	Y	-	-
COMMERCIAL OPERA	TION	manufacture state	-

### AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-333

UNIT JAFNPP

DATE September 1981

COMPLETED BY E. Zufelt

TELEPHONE (315)342-3480

AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
763	17	279
758	18	682
756	19	574
657	20	705
26	21	731
0	72	761
0	23	757
74	24	750
546	25	755
608	26	753
89	27	753
0	28	747
0	29	751
0	30	749
0	31	745
0		

SUMMARY: Unit operated this reporting period with two shutdowns.

One on August 5, 1981 due to damaged RPS cable and one on August 11, 1981 for excessive leakage from relief valves.

#### UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. UNIT NAME DATE

September 1981 COMPLETED BY E. Zufelt TELEPHONE (315)342-3840

### REPORT MONTH AUGUST 1981

No.	Date	Typel	Duration (Hours)	Reason-	Method of Shutting Down Reactor3	Licensee Event Report #	System Code <sup>4</sup>	Component Code5	Cause & Corrective Action to Prevent Recurrence
10	810805	F	82.9	Н	2	NA	IA	ELECON	RPS cable damaged. Repaired cable.
11	810811	F	139.9	A	2	NA	cc	VALVEX	Excessive leakage from relief valves. Repaired valves.

F: Forced

S: Scheduled

Reason:

A-Equipment Failure (Explain) B-Maintenance of Test

C-Refueling

D-Regulatory Restriction E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain) H-Other (Explain)

Method:

4 !-Manual

2-Manual Scram.

3-Automatic Scram.

4-Other (Explain)

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

5

Exhibit I - Same Source

NARRATIVE SUMMARY OF OPERATING EXPERIENCES AUGUST 1981

There were two (2) shutdowns during this reporting period. The first one occured on August 5, 1981 when the RPS cable was damaged while repairing electrical penetration seal material. The cable was repaired and the unit was back on line August 8, 1981.

The second shutdown occured on August 11, 1981 when excessive leakage was discovered from SRV-71F. The valve was repaired and the unit was back on line August 17, 1981.

## SAFETY RELATED ELECTRICAL & MECHANICAL MAINTENANCE SUMMARY

AUGUST, 1981

DATE	SYSTEM	WORK REQUEST # COMPONENT #	HOW DETECTED	CAUSE OF MALFUNCTION	ACTION TAKEN TO PRECLUDE RECURRENCE	REPAIR TIME HOURS
7/27	76	10053 Scott Air Pack Compressor	OPS	N/A	Performed 3 month, 6 month & 12 month preventative maintenance	8
7/27	00	8864 UT Calibra- tion Blocks	QC	Wrong stamping	Restamped NO's	1
8/11	24	13031 Rx Track Bay Door	OPS	Limit switches out of adjustment caused failure of door to open electrically	Readjusted limits	3
8/14	23	13127 AOV-53	Visual	Blown bonnet gasket	Replaced bonnet gasket - torqued	9
8/14	34	13525 SOV-111A	OPS	Worn Internals caused valve to blow by	Replaced valve	11
8/14	34	13526 SOV-111B	OPS	Open coil	Replaced coil	8
8/14	11	10391 12961 Accumulators 7A & B	OPS	Leaking bladders-Age	Replaced bladders	5
8/14	03	13551 HCU 46-31 111 valve	OPS	Packing blown-Age-Wear	Replaced valve	8

### SAFETY RELATED ELECTRICAL & MECHANICAL MAINTENANCE SUMMARY

AUGUST,1981

DATE	SYSTEM	WORK REQUEST # COMPONENT #	HOW DETECTED	CAUSE OF MALFUNCTION	ACTION TAKEN TO PRECLUDE RECURRENCE	REPAIR TIME HOURS
8/15	16-1	13545 AOV-101B	OPS	Faulty solenoid valve	Replaced solenoid valve	24
8/16	29	13555 AOV-86A	OPS	MSIV failed to open	Replaced 4-way valve	52
8/16	29	12402 AOV-86A	OPS	Open indicating light would not go out	Adjusted limit switches	6

### MAINTENANCE SUMMARY

AUGUST 1981 I&C

DATE	SYSTEM	WORK REQUEST # COMPONENT #	HOW DETECTED	CAUSE OF MALFUNCTION	RESULTS OF MALFUNCTION	ACTION TAKEN TO PRECLUDE RECURRENCE	REPAIR TIME HOURS
8/12/81	02	7003 TE-145A	I&C	Loose connection	Erroneous high temperature indication	Tightened connection	3.0
8/15/81	02	12987 TE-112B	OPS	Cut thermocouple	No temperature indication	Replaced thermocouple	32.0
8/3/81	02-3	7000 LIS-72C	I&C	Switch against stop	Unable to adjust to correct set point	Realigned magnetic switches	4.0
8/3/81	07	12809 P.R. 46D	OPS	Age,use	Paper does not track correctly	Lubricated and adjusted paper drive	3.0
8/5/81	07	13030 IRM G	OPS	Loose cable connector at pre-amp	Spiking upscale causing spurious 1/2 scrams	Repaired cable connector	3.0
8/5/81	07	13026 IRM F-HUPS	I&C	Defective filter	Unstable high voltage	Replaced filter	4.0
8/7/81	07	13045 IRM G	OPS	Internal test circuit out of	Low meter indication for	Adjusted per IMP 7.3	3.0
				adjustment	internal test		
8/12/81	07	12978 P.R. 46C	OPS	Pens out of alignment	Pens sticking	Realigned pens and calibrated	4.0
7/30/81	16	12944 X-104C,D,X-111B	OPS	Slow leak	Low pressure in electrical	Repressurized penetrations	6.0
					penetration		
8/5/81	17	13029 RM 350	OPS	Loose knob	Set point knob not changing set point	Realigned knob	7.0

### MAINTENANCE SUMMARY

AUGUST 1981 I&C

DATE	SYSTEM	WORK REQUEST # COMPONENT #	HOW DETECTED	CAUSE OF MALFUNCTION	RESULTS OF MALFUNCTION	ACTION TAKEN TO PRECLUDE RECURRENCE	REPAIR TIME HOURS
8/15/81	17	13533 RIS 456A,B	OPS		Mis - match between A & B	Corrected wiring error	3.0
8/14/81	23	7001 TE-92A	I&C	Loose	No remote indication	Tightened connection	10.0
8/15/81	23	13552 TE-92B	OPS	Broken temp.	No remote indication	Replaced temp. element	10.0
7/31/81	27	10088 R 102	OPS	Out of alignment and defective amplifier	Recorder not working	Realigned, replaced amp, calibrated	25.0
8/22/81	27	13581 OAZ-101A	OPS	Drift	Oxygen reading low		2.0
8/14/81	29	13527 AOV 86B	OPS	Change out of filter	Slow closure too slow	Adjusted for proper time	4.0