

NOTICE OF VIOLATION

Huron Memorial Hospital  
Bad Axe, Michigan

License No. 21-17093-01  
Docket No. 030-12179

As a result of the inspection conducted on December 12, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, (1990)(Enforcement Policy) the following violations were identified:

1. 10 CFR 35.22(a)(2) requires that the Radiation Safety Committee meet at least quarterly.

Contrary to the above, from May 16, 1988, to January 25, 1989, the licensee's Radiation Safety Committee did not meet during the third and fourth quarters of 1988.

This is a Severity Level IV violation (Supplement VI).

2. 10 CFR 35.50(b)(4) requires that a licensee test each dose calibrator for geometry dependence upon installation over the range of volumes and volume configurations for which it will be used.

Contrary to the above, the licensee did not test the dose calibrator for geometry dependence when it was installed on August 2, 1989.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

December 24, 1990  
Dated

Roy J. Caniano  
Roy J. Caniano, Chief  
Nuclear Materials Safety  
Section 2