## APPENDIX A

## NOTICE OF VIOLATION

Harold MacQuinn, Inc. Ellsworth, Maine 04605 Docket No. 030-29120 License No. 18-27806-01

As a result of the inspection conducted on November 13, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1990), the following violations were identified:

A. License Condition No. 15 of NRC License No. 18-27806-01 requires that a physical inventory be conducted every six (6) months to account for all sources and/or devices received and possessed under the license.

Contrary to the above, as of November 13, 1990, the required six (6) month physical inventories have not been conducted to account for the three (3) sealed sources possessed by the licensee.

This is a Severity Level IV violation. (Supplement IV)

B. License Condition No. 16 of NRC License No. 18-27806-01 requires that licensed material be used in accordance with statements, representations, and procedures contained in an application dated March 27, 1986.

Item No. 7 of the application, names a specific individual who is responsible for the radiation safety program.

Contrary to the above, the named individual is no longer responsible for the radiation safety program. Specifically, this individual's employment has been terminated by the Licensee on January 11, 1990.

This is a Severity Level IV violation. (Supplement IV)

Pursuant to the provisions of 10 CFR 2.201, Harold MacQuinn, Inc. is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.