

# Professional Quality Testing Co.

Laboratory: 801 Steel Plaza • Building 2B  
New Kensington, PA 15068  
(412) 337-9810

July 31, 1990

Nuclear Regulatory Commission  
Region 1  
475 Allendale Rd.  
King of Prussia, Pa. 19406

Attn: Mr. John R. White

Re: Docket No. 030-31072  
License No. 37-28367-01

Dear Mr. White,

In response to the violations identified in the above referenced Docket No., the following corrective steps have been taken:


Violation 1 Professional Quality Testing Co,s storage vault was considered to be the sealed steel, lead lined container in the mobil darkroom. This metal container is bolted through the frame of the camper and can not be removed. It also is lead lined and pad locked against public entry.

Corrective Action Upon the next filing of Professional Quality Testing Co manual change, I will change the terminology of vault to storage container in the mobil darkroom.

Violation 2 Lack of previous radiographic safety training records of an employed radiographer.

Corrective Action As of June 29, 1990, the previos training records of that individual were received from his previous employer and filed in his training records. All other personnel files were reviewed and found to contain all previous and present training records. In the future, all new employee records will be reviewed thoroughly by the R.S.O. for proper documentation.

Sincerely,

  
John C. Chabal  
Radiation Safety Officer

9101020138 901219  
REG1 LIC30  
37-28367-01 PDR