

DEC 21 1990

In Reply Refer To:
License: General License 10 CFR 150.20
Docket: 150-00043/90-01

BHP-Utah Minerals International
ATTN: R. Winder, Radiation Safety Officer
10 West 2950 South
Salt Lake City, Utah 84165-0479

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Messrs. Robert A. Brown and Gilbert L. Guerra, Jr., of this office on November 29, 1990, involving the use of a borehole logging source near White Sulfur Springs, Montana, under reciprocity with Byproduct License No. UT 1800132 issued by the State of Utah, and to the discussion of our findings held by the inspectors with members of your staff at the conclusion of the inspection.

This inspection was an examination of the activities conducted under the general license as authorized under reciprocity and as they relate to radiation safety and to compliance with the rules and regulations and the conditions of the appropriate specific license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspectors.

No violations or deviations were identified.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed By:

A. B. BEACH

A. Bill Beach, Director
Division of Radiation Safety
and Safeguards

cc:
Utah Radiation Control Program Director

RIV: NMSIS
RABrown: jt

12/10/90

NMSIS
GLGuerra
12/20/90

C: NMSIS
CLCain
12/19/90

D: DRSS
ABBeach
12/21/90

9101020399 901221
PDR STPRG ESQMT
PDR

020000

IE-07
1/1

bcc:

DMB - Original (IE-07)

RDMartin

ABBeach

LAYandell

MRodriguez, OC/LFDCB (4503)

*WLFisher

*CLCain

*RABrown

*GLGuerra

*NMSIS

*MIS System

*RIV Files (2)

*RSTS Operator

*REHall, URFO

*W/766