HOMESTAKE MINING COMPANY

P.O. BOX 98 GRANTS, NEW MEXICO 87020 (505) 287-4456

November 29, 1990

RETURN ORIGINAL TO POR, HQ.

41 - 8903

Mr. Ramon Hall, Director Uranium Recovery Field Office U.S. Nuclear Regulatory Commission Post Office Box 25325 Denver, Colorado 80225

Re: License No. SUA-1471

DOCKETED NOV 30 1990

Dear Mr. Hall:

04008903380E

As per the annual soil sampling and gamma survey report submitted September 28, 1990, the attached map shows the results of the resampling performed.

The area on the NW sector exceeding 10.5 pCi/g Ra226 has been scraped and is being resampled to insure the area is below 10.5 pCi/g Ra226. The area being scraped is believed to be an isolated area previously missed during the initial soil cleanup.

The resurvey of all other areas, where initial samples indicated Ra226 greater than 10.5 pCi/g, show to be well below 10.5 pCi/q Ra226.

If you have any questions or comments please don't hesitate to contact me.

Very truly yours,

HOMESTAKE MINING COMPANY

mak P. Ohles

Radiation Protection Administrator

addl Sign G1-0114

9101030209 901129 PDR ADDCK 04008903

MDH: jq

Attachment

xc: F. Craft

w/o attachment

DESIGNATED ORIGINAL

Mary C. Hood

An Equal Opportunity Employer