

October 27, 1982

Log No. K82-1545 File: RR2 (NP-33-82-61)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 82-052 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: September 27, 1982

Enclosed are three copies of Licensee Event Report 82-052 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Torry D. Munay/ 50

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station


TDM/kl

enclosures

cc: Mr. Richard DeYoung Office of Inspection and Enforcement Encl: 30 copies

Mr. Norman Haller, Director Office of Management and Program Analysis Encl. 3 copies

Mr. Tom Peebles NRC Resident Inspector Encl: 1 copy



THE TOLEDO EDISON COMPANY EDISON PLAZA

LAZA 300 MADISON AVENUE

TOLEDO, OHIO 43652

1822 1 1982 NOV